DOUV Step Noir

Work Örder ID 57568

April 8, 2010 12:48:49 PM

Quality Control

Page 1

Item ID: Revision ID: Item Name:	DSI 9410-011 Step Modification				Accept		S	Setup	Start Stop				
Start Date: Required Date:	4/08/10	Start Qty: 2.00 Req'd Qty: 2.00				Cust Item I Customer:	D:	- §			·	1 (68) 161 11	618 18 (681 1981
Approvals:	Process Plan	n:	Date:		Tooling: SPC (Y/N):		ate:	- \ 	I	Run	Start Stop		
Sequence ID/ Work Center II		Operation Description	· · · · · · · · · · · · · · · · · · ·		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Rejo Qty		Reject Number	Insp. Stamp
Draw Nbr		ision Nbr											
DSI 9410 100 DC Document Control	<u>B</u>	Memo Photocop CHG002		labels per Pl	0.00 0.00	lou/12		•	4	Cor	. B	<u>s lo</u>	101/12
Packaging Packaging		Pick Kit Memo			0.00				(1	[] [w]q	/ //_/	2	
120 		QC4- 100% Inspect k	its for completer	ness	(λ) 0.00 colour	Â			(PL)			

April 8, 2010 12:48:49 PM

Item ID:

DSI 9410-011

Accept



Setup Start



Revision ID:

Start Date:

Item Name:

Required Date: 4/12/10

Step Modification

4/08/10

Start Qty: 2.00

Req'd Qty: 2.00

Operation

Description



Cust Item ID: Customer:

Reference:

Approvals:

Process Plan:

QC:

Date: _____

Date: _____

SPC (Y/N):

Set Up/

Run Hours

Tooling:

Date:

Draw

Number

Date:

Draw

Rev.

Plan

Code

Start



Stamp

Sequence ID/ Work Center ID

130

Packaging Packaging

Memo

0.00

0.00

Identify and pack for shipping as per PPP DSI 9410-011

Location:

PPP rev:

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Run

Accept

Qty

Stop

Stop

Reject Insp.

Number

Reject

Qty

10/04/1375) 11/0-13-4

Picklist.Print April 8, 2010 12:48:48 PM Work Order ID: 57568 Parent Item: DSI 9410-011 Parent Item Name: Step Modification **Start Date: 4/08/10** Required Date: 4/12/10 Comments: IPP RevA: New issue DD verified by:EC IPP rev:B as per dwg RevB DD Start Qty: 2.00 Required Qty: 2.00 10.03.03 verified by:EC Component Item ID/ Replacement Mfg/ Bin **Primary** Last Route Unit of Oty on Remaining Qty Date Seq ID Hand Item Name-Purch Item Location Location Measure Qty To Pick Issued Issued Item ID Purchased No 110 Each 499.0000 16.0000 Warehouse Loc Qty Loc Code Location Main Warehouse ST358 499 114239 40 114292 459 No 110 Each 0.0000 32.0000 Washer

110

110

0.0000

0.0000

Each

sf

8.0000

D2732-030

Manufactured

No

No

coult(4) at 3.00" per kit! -> messacos soloul 12

Manufactured

Rubber Cushion (per sq ft)

(D3595-200-300) Cut(2) at 2.00" X 3.00" as per dwg D3595 (per kit)

0.1666 B39963

56516

Status

April 8, 2010 12:48:48 PM

Work Order ID: 57568

Parent Item:

DSI 9410-011

Parent Item Name:

Step Modification

Comments:

IPP RevA: New issue DD verified by:EC

10.03.03 verified by:EC



IPP rev:B as per dwg RevB DD

Start Date: 4/08/10

Required Date: 4/12/10

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name_ MS21042L4 & X

Replacement Item ID

Mfg/ Purch Purchased Bin **Primary** Item Location No

Last Location Route Seq ID 110

Unit of Measure Each

Qty on Hand 1,566.000 16.0000

Remaining Oty Qty To Pick Issued Date Issued /

Status

Warehouse	Loc Qty	Loc Code
Location		· ·
Main Warehouse		·
ST139	2	·

111827 2 Main Warehouse ST300 1564

> 113422 556 114108 1000 9063 8

DART SERVICE INSTRUCTION

TO AMEND DRAWING D350-591 REV. F REF. CANADIAN STC: SH92-6

FAA STC: SH967NE



TO IMPROVE THE FIT OF THE D350-591-311/-312 STEPS, IT IS ACCEPTABLE TO INSTALL THE DSI 9410-011 KIT. INSTALL THE D2732-030 CUSHION (AFT CROSSTUBE) AND D3595-200-300 CUSHION (FWD CROSSTUBE) AS SHOWN IN FIGURE 1 IN PLACE OF THE D2856-400-720 ABRASION STRIP CALLED OUT ON DRAWING D350-591 REV. F.

FOR CUSTOMERS WHO HAVE PREVIOUSLY INSTALLED D2856-400-720 ABRASION STRIPS REMOVE THE ABRASION STRIPS IN ACCORDANCE WITH ICA-D350-591.

PRIOR TO INSTALLING THE DSI 9410-011 KIT.

DSi 9410-011 KITS WILL BE INCLUDED WITH D350-591-311/-312 STEPS AT CHANGE 002 AND SUBSEQUENT.

QTY -041	PART NUMBER	DESCRIPTION
Х	DSI 9410-011	STEP MODIFICATION KIT
4	D2732-030 i	CUSHION
2	D3595-200-300 /	CUSHION
8_	AN4-15A.	BOLT
þ 6	AN960JD416/	WASHER
8	MS21042L4	NUT (OR MS21042-4)

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: D. SHEPHERD (DE # 02)

DATE: 08.09.08

CERT. NO.: SH92-6

ISSUE NO.: 10

В		1 DELETE RE	AJS	08.09.08			
Α	NEW IS	SSUE		PH	08.03.27		
REV.			DESCRIPTION	BY	DATE		
DESIGN		#35	DART AEROSP	ACE	LTD		
DRAWN AUS			HAWKESBURY, ONTARIO, CANADA				
CHECKED			DRAWING NO.	,	REV. B		
MFG. APPR. N/A			DSI 9410	SHEET 1 OF			
APPROVED 10			TITLE		SCALE		
DE APPR.			STEP MODIFICATION KIT NTS				
DATE	08.0	9.08	COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY DURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WITHTEN PERMISSION FROM DART AEROSPACE LTD.				

Dart Aerospace Ltd

										•			
W/O:		WORK ORDER CHANGES											
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
						·							
 													
Part No	•	PAR #:	Fault Categ	jory:	NCI	R: Yes	No DQ	4 :	Date:				
			Disposition: QA										
NCR:				R NON-CONFORM									
DATE	STEP	Description of NC	Corrective Action Section B			Verifica			ion Approval	Approval			
	Section A		Initial Chief Eng	Action Description Chief Eng			Sign & Section C			QC Inspector			
										-			
,								_					
								,					

NOTE: Date & initial all entries